


Sensor Valve Linkage Installation Instructions

L31185
95220003
Rev. 10/02

⚠ CAUTION
Not following these installation instructions may result in damage to equipment and could cause personal injury.

For proper Sensor Valve adjustment procedures refer to EDL-ARF Service Manual or contact the Haldex Technical Services Department at 1-800-643-2374.

Sensor Valve Linkage Assembly
Part Number 90554896
Installation Diagram



Note: Linkage length = 4 3/4" ± 1/8" (center to center)



Commercial Vehicle Systems

World Headquarters
10930 N. Pomona Avenue
Kansas City, MO 64153-1297
Phone: (816) 891-2470
Fax: (816) 891-9447

North American Sales Division
10707 N.W. Airworld Drive
Kansas City, MO 64153-1215
Phone: (816) 891-2470
Fax: (816) 880-9766

Haldex Limited
525 Southgate Drive, Unit 1
Guelph, Ontario CANADA
N1G 3W6
Phone: (519) 826-7723
Fax: (519) 826-9497




Sensor Valve Linkage Installation Instructions

L31185
95220003
Rev. 10/02

⚠ CAUTION
Not following these installation instructions may result in damage to equipment and could cause personal injury.

For proper Sensor Valve adjustment procedures refer to EDL-ARF Service Manual or contact the Haldex Technical Services Department at 1-800-643-2374.

Sensor Valve Linkage Assembly
Part Number 90554896
Installation Diagram



Note: Linkage length = 4 3/4" ± 1/8" (center to center)



Commercial Vehicle Systems

World Headquarters
10930 N. Pomona Avenue
Kansas City, MO 64153-1297
Phone: (816) 891-2470
Fax: (816) 891-9447

North American Sales Division
10707 N.W. Airworld Drive
Kansas City, MO 64153-1215
Phone: (816) 891-2470
Fax: (816) 880-9766

Haldex Limited
525 Southgate Drive, Unit 1
Guelph, Ontario CANADA
N1G 3W6
Phone: (519) 826-7723
Fax: (519) 826-9497

Rev. 10/02 ART ONLY L31185 (95220003)




Sensor Valve Linkage Installation Instructions

L31185
95220003
Rev. 10/02

⚠ CAUTION
Not following these installation instructions may result in damage to equipment and could cause personal injury.

For proper Sensor Valve adjustment procedures refer to EDL-ARF Service Manual or contact the Haldex Technical Services Department at 1-800-643-2374.

Sensor Valve Linkage Assembly
Part Number 90554896
Installation Diagram



Note: Linkage length = 4 3/4" ± 1/8" (center to center)



Commercial Vehicle Systems

World Headquarters
10930 N. Pomona Avenue
Kansas City, MO 64153-1297
Phone: (816) 891-2470
Fax: (816) 891-9447

North American Sales Division
10707 N.W. Airworld Drive
Kansas City, MO 64153-1215
Phone: (816) 891-2470
Fax: (816) 880-9766

Haldex Limited
525 Southgate Drive, Unit 1
Guelph, Ontario CANADA
N1G 3W6
Phone: (519) 826-7723
Fax: (519) 826-9497

Rev. 10/02 ART ONLY L31185 (95220003)



Instrucciones para la instalación del enganche de la válvula de sensor

L31185
95220003
Rev. 10/02

⚠ PRECAUCIÓN


Si no se siguen estas instrucciones de instalación, podría provocar daños del equipo y ocasionar heridas a las personas.

Para conocer los procedimientos de ajuste apropiado de la Válvula de Sensor, consulte el Manual de Servicio EDL-ARF o comuníquese con el Departamento de Servicios Técnicos de Haldex al teléfono 1-800-643-2374.

Montaje del enganche de la válvula de sensor

Número de parte 90554896

Diagrama de instalación



Nota: Largo del enganche - 4 ¾" ± 1/8" (de centro a centro)



Commercial Vehicle Systems

World Headquarters
10930 N. Pomona Avenue
Kansas City, MO 64153-1297
Teléfono: (816) 891-2470
Fax: (816) 891-9447

North American Sales Division
10707 N.W. Airworld Drive
Kansas City, MO 64153-1215
Teléfono: (816) 891-2470
Fax: (816) 880-9766

Haldex Limited
525 Southgate Drive, Unit 1
Guelph, Ontario CANADA
N1G 3W6
Teléfono: (519) 826-7723
Fax: (519) 826-9497



Instrucciones para la instalación del enganche de la válvula de sensor

L31185
95220003
Rev. 10/02

⚠ PRECAUCIÓN


Si no se siguen estas instrucciones de instalación, podría provocar daños del equipo y ocasionar heridas a las personas.

Para conocer los procedimientos de ajuste apropiado de la Válvula de Sensor, consulte el Manual de Servicio EDL-ARF o comuníquese con el Departamento de Servicios Técnicos de Haldex al teléfono 1-800-643-2374.

Montaje del enganche de la válvula de sensor

Número de parte 90554896

Diagrama de instalación



Nota: Largo del enganche - 4 ¾"±1/8" (de centro a centro)



Commercial Vehicle Systems

World Headquarters
10930 N. Pomona Avenue
Kansas City, MO 64153-1297
Teléfono: (816) 891-2470
Fax: (816) 891-9447

North American Sales Division
10707 N.W. Airworld Drive
Kansas City, MO 64153-1215
Teléfono: (816) 891-2470
Fax: (816) 880-9766

Haldex Limited
525 Southgate Drive, Unit 1
Guelph, Ontario CANADA
N1G 3W6
Teléfono: (519) 826-7723
Fax: (519) 826-9497



Instrucciones para la instalación del enganche de la válvula de sensor

L31185
95220003
Rev. 10/02

⚠ PRECAUCIÓN


Si no se siguen estas instrucciones de instalación, podría provocar daños del equipo y ocasionar heridas a las personas.

Para conocer los procedimientos de ajuste apropiado de la Válvula de Sensor, consulte el Manual de Servicio EDL-ARF o comuníquese con el Departamento de Servicios Técnicos de Haldex al teléfono 1-800-643-2374.

Montaje del enganche de la válvula de sensor

Número de parte 90554896

Diagrama de instalación



Nota: Largo del enganche - 4 ¾" ± 1/8" (de centro a centro)



Commercial Vehicle Systems

World Headquarters
10930 N. Pomona Avenue
Kansas City, MO 64153-1297
Teléfono: (816) 891-2470
Fax: (816) 891-9447

North American Sales Division
10707 N.W. Airworld Drive
Kansas City, MO 64153-1215
Teléfono: (816) 891-2470
Fax: (816) 880-9766

Haldex Limited
525 Southgate Drive, Unit 1
Guelph, Ontario CANADA
N1G 3W6
Teléfono: (519) 826-7723
Fax: (519) 826-9497